ACCIDENT INFORMATION SUMMARY

DPS 38 C Rev. 7/94



DEPARTMENT OF PUBLIC SAFETY DIVISION OF STATE POLICE

NO. & TYPE OF VEHICLES INVOLVED 2 CAR	OTHER(S) INVOLVED	
(passenger car, truck, bus, etc.)	(pedestrian, pole, bridge abutino	int, etc.)
CASE NUMBER DPS-05-010137 DATE FEBRUAR	RY 24, 2005 TIME 2307	
TOWN BOZRAH (T013) ROUTE RT 2 W	EST TROOPER SUTHERLAND #	1047
UTILITY POLE NAME & #	UTILITY POLE NAME & #	
OP # 1 MORAN, JOHN D.O.B. 07/26/49	OP#2 BEATTY, JEREMY	O.O.B. 07/27/71
ADDRESS 1499 SILAS DEAN HWY #142	ADDRESS 136 MOTT RD	
TOWN ROCKY HILL 06067 STATE CT	TOWN EAST HAMPTON 06424 STA	TECT
OP. LIC. 071985942 STATE CT	OP. LIC. 076160046 STA	TE CT
OWNER # 1 SAME	OWNER#2 SAME	
ADDRESS SAME ZIP 06067	ADDRESS SAME	ZIP 06424
REG. 301-TFD STATE CT	REG. 2CH112 ' STA	TE CT
MAKE AND TYPE VEH. NISSAN MAXIMA YEAR 1998	MAKE AND TYPE VEHCHEVY SILVARADO PICKUP	YEAR 2002
TOWED TO TROOPK FITCHVILLE AUTO	TOWED TO TROOP K FITCHVILLE AUTO	
VIN# JN1CA21D9WM908488	VIN# 2GCEK19V021321399	
OCCUPANTS NONE AGE	OCCUPANTS NONE	AGE
	4 700 400	
AIR BAGS/SEATBELT	AIR BAGS/SEATBELT	
POL. # 325-53-62 INS. AIG AUTO INS. CO.	POL. # 951106-20GN INS. AMICA	A INS. CO.
DAMAGE HEAVY DRIVER SIDE	DAMAGE HEAVY FRONT END	
OP#3 D,O.B	OP#4	D.O.B.
ADDRESS	ADDRESS	
TOWN STATE	TOWN ST/	
OP. LIC. STATE	OP. LIC. STA	
OWNER#3	OWNER#4	
ADDRESS ZIP	ADDRESS	ZIP
REGSTATE	REG. STA	ATE
MAKE AND TYPE VEH. YEAR	MAKE AND	YEAR .
TOWED TO	TOWED TO	
VIN#	VIN#	
OCCUPANTS AGE	OCCUPANTS	AGE
The second secon		
POL.# INS.	POL.#. INS.	
DAMAGE	DAMAGE :	
	The state of the s	

PAGE 1-TROOP (COMPLETE REVERSE SIDE)
OTHER PAGES - OPERATOR'S COPY

# I AMBULANCE	# 2 AMBULANCE
HOSPITAL	HOSPITAL
INJURIES	INJURIES
# 3 AMBULANCE	# 4 AMBULANCE
HOSPITAL	HOSPITAL
INJURIES	INJURIES
FATALITIES: DO NOT RELEASE UNLESS NEXT OF KIN NOTIFIED: OPERATOR #I VES NO NOTIFIED	NOTIFIED
VES NO	
ARRESTED	ARRESTED Operator #2 14-227a, 14-222, 14-218a*, 53a-56b
WARNED	WARNED
Do not release names of p	

BRIEF DESCRIPTION OF ACCIDENT

Vehicle #1 while traveling west on RT2 approximately 1/5 mile west of exit 23 in Bozrah CT, spun out of control on the snow covered highway and was struck on its driver side by the front end of vehicle #2, which was traveling west on RT 2 behind vehicle #1.

Operator #1 was trapped inside vehicle #1 and was pronounced dead at the scene. Operator #2 did not report any injuries and refused treatment at the scene.

Operator #2, after failing a field sobriety test, was subsequently arrested for violations of CT Gen Stat 14-227a operating under the influence of drugs/alcohol or both, 14-222 reckless driving, 14-218a* traveling too fast for conditions, and 53a-56b manslaughter in the second degree.

Anyone with information regarding this accident is encouraged to contact Trooper Sutherland at Troop K in Colchester at 860-537-7500

